

Vaika kayalaka abhiyankaravara
Kabhidi No.4 Building Sub
Division Public Works Department Bangalore 560001

Phone Number 08022267585
E Mail: aceno4bldg@gmail.com

Department of Public works

To
Secretary,
Universal Education Society(R)
Site No, CA-06,
West of Chord road,
2nd Stage, Bangalore-58

If So,
Subject: Regarding issue of safety certificate for school building

Reference: 1: Your Request letter dated: 17.02.2023
2. Government of Karnataka Additional Secretary, Public works Department circular no:
daca5902019 tech: 06.05.2022

With reference to the above: Universal Education Society (R), Site no. CA-06, West of Chord road 2nd Stage, Bangalore 58 and NEW CAMBRIDGE INTERNATIONAL PUBLIC SCHOOL, CA Site 6 (p), WOC road, 2nd Stage, Mahalakshmiipuram Bangalore 560058 Requested in the letter referred to (1) to issue safety certificate for the school building. Building situated at New Cambridge International Public School, CA Site 6 (P), WOC Road, 2nd Stage, Mahalakshmiipuram, Bangalore-560058 date:2/02/2023, Engineer and Secretary of the Institute Mr Yogesh.N Inspected the interior and exterior of the building with the help of surveyors, the said building was Constructed in 2013 with basement and ground floor and first floor in 2020.

The commissioner Bangalore Development Authority Map Divisions Bangalore approved the constructions of the three storied building with basement + ground floor. However, the building has ground floor and first floor granite flooring aluminum windows and wooden doors and ground floor with steel windows and wooden doors. 22 classrooms + 5 labs on the ground and ground floor of the said building and toilets with 13 class rooms on the first floor are found.

Due to the lack of test reports of concrete, Steel, cement and sand etc: materials used in building construction work related to the building you have attached the reports of two types of Non Destructive Tests as indicated in the government circular of reference (2) with the request letter tested by Karnataka Material Test House Pvt ,Ltd NO 778 /44, Gokula 1st stage 2nd phase 8th cross, Triveni Road Yeshwantpur ,Bangalore Ultrasonic Test Result and Rebound Hammer Test result reported has been sent.It is concluded that the structure is in sound condition is confirmed.

You have submitted the following necessary documents.

1. Sanction Plan
2. Ultrasonic Pulse Velocity Test Report
3. Rebounded Hammer Test result.
4. Tax paid certificate

For a School/College in an urban area as indicated in Order No (2) of the Government circular of reference (2)- Rs 5000.00 as fee by the said organization in the background) has paid Rs 5000 vide receipt noCR022 3005 900 545874 dated 20/02/23.

All the floors and important part of the building of the said institution were inspected. However, Dampness, cracks found in the walls and ceiling of the building and Karnataka Material Test Housing private limited to take immediate action to rectify the deficiencies pointed out in the report. The responsibility of maintaining the building rests with the said organization and this certificate is subject to revocation at any time.



If any changes or additions are made in the building in the near future, The affidavit is automatically cancelled. Therefore the said certificate is issued to Universal Education Society (R). Site No CA 6, West Of Chord Road 2nd Stage Bangalore 560058 New Cambridge International Public School, CA Site 6(p) WOC Road, 2nd stage Mahalakshmiपुरam, Bangalore 560058 to use the school building here for Educational Purpose only

You're sincerely,
Office of the Assistance Executive Engineer,
No. 4, Building Division
Bangalore 560001

Kannada to English translated by

B.S. Jayashree.
Senior Principal / Advisor
New Cambridge International Public School
C.A. Site No.6 (P), West of Chord Road
2nd Stage, Mahalakshmiपुरam
BANGALORE-560 086



ATTESTED BY ME

27/1/24
R. VISHWANATH, B.Com, LL.B.
ADVOCATE AND NOTARY
No. 14/50, 12th Main, 2nd Block
Near ESI Hospital & Sri Anjaneya Temple
Rajajinagar, BANGALORE - 560 010
Cell : 9845278488